


LBW-420-1 to Door Monitor Wiring

Door Monitor

Jumper must be on J3 pins 2 and 3

LBW-420-1



White Wire

4 to 20Ma signal wire.

Sig +

sensor 4 to 20Ma (-)

Green Wire

4 to 20Ma return wire.

Sig -

24VDC - in

Red Wire

Back Light + wire.

B/L +

24VDC + in

Black Wire

Back Light - wire.

B/L -

24VDC - in

